

FIG. 1





FIG. 2



ERROR AT THE TIME OF INSTALLATION  
 DEFORMATION DUE TO AGING AND THERMAL VARIATION  
 (DEFORMATION OF HIGH TEMPERATURE PIPE)  
 (NOTE THAT A SPACE BETWEEN THE WEDGE AND  
 THE PIPE IS FILLED WITH HIGHLY VISCOUS GREASE  
 OR METAL COUPLANT)

3 / 9

FIG. 3 (b)




FIG. 3 (a)




FIG. 3 (c)






FIG. 4



5 / 9

FIG. 5



F I G. 6




FIG. 7




FIG. 8






FIG. 9

